



## Broca ciega de conexión rápida para taladradoras

**CMT ORANGE TOOLS®**


**HW Z2 V2 RH LH**



Afilado con precortadores negativos



**310**

D mm	I mm	L mm	S mm		CÓDIGO Rotación derecha	CÓDIGO Rotación izquierda
4	27	57,5	10x27	50	<b>310.040.11</b>	<b>310.040.12</b>
4,5	27	57,5	10x27	50	<b>310.045.11</b>	<b>310.045.12</b>
4,76	27	57,5	10x27	50	<b>310.047.11</b>	<b>310.047.12</b>
5	27	57,5	10x27	50	<b>310.050.11</b>	<b>310.050.12</b>
5,1	27	57,5	10x27	50	<b>310.051.11</b>	<b>310.051.12</b>
5,2	27	57,5	10x27	50	<b>310.052.11</b>	<b>310.052.12</b>
5,55	27	57,5	10x27	50	<b>310.055.11</b>	<b>310.055.12</b>
6	27	57,5	10x27	50	<b>310.060.11</b>	<b>310.060.12</b>
6,35	27	57,5	10x27	50	<b>310.064.11</b>	<b>310.064.12</b>
6,5	27	57,5	10x27	50	<b>310.065.11</b>	<b>310.065.12</b>
7	27	57,5	10x27	50	<b>310.070.11</b>	<b>310.070.12</b>
8	27	57,5	10x27	50	<b>310.080.11</b>	<b>310.080.12</b>
8,2	27	57,5	10x27	50	<b>310.082.11</b>	<b>310.082.12</b>
9	27	57,5	10x27	50	<b>310.090.11</b>	<b>310.090.12</b>
9,52	27	57,5	10x27	50	<b>310.095.11</b>	<b>310.095.12</b>
10	27	57,5	10x27	50	<b>310.100.11</b>	<b>310.100.12</b>
11	27	57,5	10x27	10	<b>310.110.11</b>	<b>310.110.12</b>
12	27	57,5	10x27	10	<b>310.120.11</b>	<b>310.120.12</b>
12,7	27	57,5	10x27	10	<b>310.127.11</b>	<b>310.127.12</b>
13	27	57,5	10x27	10	<b>310.130.11</b>	<b>310.130.12</b>
14	27	57,5	10x27	10	<b>310.140.11</b>	<b>310.140.12</b>
15	27	57,5	10x27	10	<b>310.150.11</b>	<b>310.150.12</b>
16	27	57,5	10x27	10	<b>310.160.11</b>	<b>310.160.12</b>

Recambios

Opcional

